

1035Z 3 JAN 61

ROUTING
SECRET

DB
R1

DIRECTOR

25X1

FROM

ACTION: DPD (1-2-3-4-5-6-7-8-9-10)

INFO: S/C (11)

CLZ 25X1

25X1

TOR: 1035Z 3 JAN 61

INITIAL WHEN READ

ROUTINE

25X1

IN-41162

13

25X1

25X1

1. TO MESSERS

FROM MESSERS

3 JAN 61.

2. MSN G-3013, ARTICLE 343, 2 JAN 61, [] TO 022320Z, LAND 030440Z.

25X1

3. B-CONFIG SN-3, HS-732 SN-50, F/16, 1/150 TOT MODES 1 AND 4, LOW SPEED GEAR. EXPOSURE COUNTER 521, LIFE CYCLE 543.

25X1

4. [] STATED DURING PRE-MISSION CYCLING AT ALTITUDE D-LITE WENT OUT AFTER 45 SEC AFTER SEVERAL ATTEMPTS TO RESTART IN MODE 1, HE TRIED MODE 4 AND INDICATOR LITES PERFORMED NORMALLY. HE AGAIN TRIED MODE 1 AND THE CONFIG. OPERATED NORMALLY THEREAFTER. BELIEVE SCHEDULED MISSION WAS 100 PERCENT. SHUTTER AND B-CONFIG OPERATED NORMALLY ON PRE- AND POST-FLIGHT.

5. EQUIPMENT BAY WAS EXCEEDINGLY WET AFTER LANDING.

6. NO ROLL, PITCH, TURBULENCE OR RADIO NOISE.

7. TRACKER SN-13 APPROX 550 FT.

8. D/S GOOD.

9. WIRING CHECKED ON SN-13 AND SN-4 TO S804A OK.

END OF MESSAGE

SECRET